

MONUMENT RECORD

Corner I.D. #

R-32



R-8

STATE OF INDIANA - COUNTY OF MONROE

Section Eleven (11), Township 9 North, Range 1 East

Monument Description & Remarks: Stone found at the NE corner of SW 1/4 of
SW 1/4. Stone was 4" x 10" x 5" out of ground. Steel fence post placed
beside stone. Corner witnessed 4/5/82.

Recovery Tie Drawing



● At Corner



Not To Scale

State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 20th day of February, 1995 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Morgan-Monroe State Forest
United States Government Agency

Bill Hahn, Property Manager
Title

Field Book:

Page:

SECTION 11, T 9 N, R 1 E

1. On April 5, 1982, I located and marked boundaries in this section as follows:

EW line of NE $\frac{1}{4}$, SW $\frac{1}{4}$; NW $\frac{1}{4}$, SE $\frac{1}{4}$, also NS line of NE $\frac{1}{4}$, SW $\frac{1}{4}$. Double boundary signs were placed at turning corners and single boundary signs on continuous lines at $\frac{1}{4}$ corner marks. A steel rod had previously been driven and marked at the NE corner of NW $\frac{1}{4}$, SE $\frac{1}{4}$. This rod appeared to be correctly placed and I used it in my boundary line search. A corner stone was found at the NE corner of SW $\frac{1}{4}$, SW $\frac{1}{4}$. I drove a steel fence post beside the stone. The stone was witnessed as follows: Rectangular stone 4" X 10", 5" out of ground, 12.75' to a 7.8" sugar maple bearing 104°^{57°E}, 9.4' to 17.7" red oak bearing 296°^{N 64° W}, 18.8' to a 15.7" white oak bearing 354°. Lines were painted boundary orange on state side.

N 06° W

Bill Hahn, Property Manager

- 2a. On June 26, 1987 a stone at the SE corner, SW $\frac{1}{4}$, SW $\frac{1}{4}$, Sec.11 was witnessed as follows:

Az	Species*	DBH(in.)	Distance(ft.)
224	Shagbark Hickory	18	20.1
062	Am. Beech	23	22.8
026	Am. Beech	14	15.9

* PK nails at base of trees

The bearing from this stone to the NE corner, SW $\frac{1}{4}$, SW $\frac{1}{4}$, Sec.11 (see entry #1) is N 0.8° W with 1 degree W declination.

- b. On Nov. 24, 1987, a U.S. real estate marker at the NE corner, S $\frac{1}{2}$, Sec.11 was witnessed as follows:

Az	Species*	DBH(in.)	Distance(ft.)
177	Red Maple	8	16.5
095	Black Oak	22	22.0
028	Yellow Poplar	10	13.9

* galvanized nails at base of trees

- c. On Nov. 29, 1987, a stone, w/ a steel fence post next to it, was witnessed at the NW corner, S $\frac{1}{2}$, Sec.11 as follows:

Az	Species*	DBH(in.)	Distance(ft.)	Comment
155	White Oak	18	1.1	w/ wire
315	Sugar Maple	13	14.8	hollow
232	White Oak	11	23.4	

* no nails at base

The bearing from this stone to the U.S. marker (2b) is N 89.5 E.